


Stepper motors (V30, V65, V250, V400, V700)

From electric motor . Cable colors




Jumper

From connection board

Servo motor (V30Q, V65Q, V30QL, V65QL)

From electric motor. Cable colors.




Jumper


From electric motor. Quick connector (Molex)

From connection board


Connection board



Molex connector



Jumper position



Jumper position on control board, when using 4-20mA, OnOff, Modbus, 3-points and digital control. Remove jumper when 0-10V control is chosen!

